



SIDE VIEW.(SCALE-1 : 2)



L– Pneumatic lines (O, P, Q, R, S,)
BR– Return Line For Cylinders In Clamped Positinon
AP– Pressure Line For Cylinders In Clamped Positinon
BP– Pressure Line For Cylinders In Loading / Unloading Station
AR– Return Line For Cylinders In Loading / Unloading Station

FLUCONN CO. G.I.D.C. VAPI.		
DRN.BY *PRAKASH*	TITLE ***ROTOR FOR 4 ST.HYD. 5STN. PNETUMATIC RDV (FOR PAIREE) V.K.***	
CHD.BY		
SCALE 1 : 1		
DATE 17/07/09		
DRG.NO FL/4ST.H–5P RDV.	MAT. M.S.	QTY. 1 NO.